MAY 1 0 1999

1994 DEC 23 AM 9: 31

SECTION

S

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Of.	COL	ners	in
	1.136	11013	

in Section

Miscellaneous

Property in Sec.

KALKA5KA Located In: Corner Code ## 1994 REMONUMENTATION T 28NR 8W **Public Land Survey** _ R __ R **Property Controlling**

REG. OF DEEDS

Register of Deeds Stamp & File Number

___ , Recorded Plat _ Private Claims __

_ R _

EUGENE FARRIER , in a field survey on Nov. 12 hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned lines 1 and 2 above were in conformance with regulations and rules therefore as required in the irrent manual of survey instructions of the United States Department of the Interior, Bureau of Land anagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 love were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a ourt of Law; established, re-established, monumented, re-monumented, recovered, found as pressed below:

OTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

G-5: Cor. common to Sec. 9, 10, 15 & 16, T28N-R8W.

1850 GLO re-survey: set post, Beech 12" N81E, 46, Beech 8" S45W, 15

7-25-00, Unknown Co Surv., set Elm post from orig. witnesses

7-02, W.S. Merrill, set stakes at cor., no accessories 3-02 to 8-11, W.S. Merrill, noted cor. several times in notes and Rec.

of Sur. of Subdivision, no accessories

6-55, G.A. Shadko, fd 1 1/4" iron pipe, no accessories.
11-61 to 9-21, Certificates of Survey, all fd 1 1/4" pipe, A.G. Erickson (Lib B of Plats Pg 47, Lib C of Plats Pg 11), C.J. Hughes (Lib 1 Pg 969), B.M. Jones (Lib 4 Pg 40)

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-5: Cor. common to Sec. 9, 10, 15 & 16, T28N-R8W. Fd 1 1/2" iron pipe. Pulled & replaced with 5/8" x 36" re-bar & aluminum cap, 0.4' below grade. No GLO witnesses were fd.

On 12-20-94 the Kalkaska Co. peer group approved the above monument as a careful and faithful reestablishment of the position of the original corner.

Ratified by Peer Group

P.A. 345 - 1990 Kalkaska County

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-5: Cor. common to Sec. 9, 10, 15 & 16, T28N-R8W.

Fd 1 1/2" iron pipe. Pulled & replaced with 5/8" x 36" re-bar & aluminum cap, 0.4' below grade.

Set nail 14" Maple, N60W, 17.22'

Set nail 6" Ironwood, N27E, 18.15'

Set nail 7" Maple, N83E, 24.20'

Fd nail 8" S. Pine, S25W, 60.77'

rveyor's Michigan License No.

____ Date 12-22-94

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 191 REVISED MAY 14, 191

GGENE D.

LAKAILA DEESSIONAL CURVEYOR No. 24594

LIBER 5 PAGE 92