## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 29 N.R. 5 W

|                         |                               | Antrim        | COUNTY |
|-------------------------|-------------------------------|---------------|--------|
| DESCRIPTION OF CORNER   | Sec. corner common to section | s 11-12-13-14 |        |
| CORNER MONUMENT         | Set 1" pipe with 4" Aluminum  | Cap           |        |
| DATE MONUMENT PLACED A  | ID WITHESSED July 22, 1966    |               |        |
| WITNESSES TO CORNER     |                               |               |        |
| N                       | 40" W. Pine stump             | S 10 R        | 29,61  |
| 13                      | 40" W. Pine stump             | N 52 W        | 41.1*  |
| CIRCLE CORNER REGISTERE | AND                           |               |        |

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set while making a survey of Section 13. Set corner at the intersection of lines parallel with the south and east lines of Section 13. This procedure was adopted as last resort, after extensive survey to recover controlling corners to north and west. Nothing to be found within four miles west or north.

Mostly Ward Land Company holdings with little occupation, or evidence of previous survey. Considered the only practical solution.

SURVEYOR'S SEAL

SIGNED LEWILL LAND SURVEYOR \$10068 DATE August 10, 1966