LAND CORNER RECORDATION CERTIFICATEFilling Requirement of Act 74, Mich. PA 1970

| For Corners In: Antrim | Located In | Corner Code # | | |
|--|---|---|---|----------------|
| (County) | Located in | Corner Code # | | |
| 1. Public Land Survey | T 29N R 6W | <u> -13</u> | | |
| 2. Property Controlling | T <u>29N</u> R 6W | <u> -12</u> | | |
| in Section | S T R | | | |
| 2 Missellaneous | S T R | | | |
| Miscellaneous Property in Section | S T R | | | |
| . , | S T R | | Register of Deeds Stamp & File Number | er |
| 4. Lot No: | Recorded Plat: | | | |
| 5. Private Claims: | | | A B C D E F G H J K L | |
| I, <u>Carl T. Kiiskila</u> , in a field survey on <u>September 18, 2000</u> do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: | | | | |
| NOTE: Not more than 2 corners, all in the same town and range, may | | | | |
| be recorded on this cer | tificate. | | 10 30 -29 -28 -27 -26 -25 - 11 12 -31 -32 -33 -34 -35 -36 - | |
| A. Description of original monument and accessories and/or subsequent restoration: | | | | |
| | ort and J.H. Mullet D.S. 1839 st 10 links | I-13 G.L.O. Set post for Wit: Sugar 1 | H. Brevoort and J.H. Mullet D.S. 1839 sections 34 and 35 I2 N13°W 21 links I2 N41°E 27 links | |
| Gosling Czubak associ data by Perla Stout as Wit: 4" Maple S25° 8" Maple N45° 6" Maple S60° | E 12.9' 'E 8.4' | 1984 | • | May 9, |
| B. Description of corner | avidence found and/or method a | survey in the Wit: N03°E 6 S70°E 6 S08°E 8 | Kral P.S. #26460 found 1" pipe while do e section 2 T28NR6W . 8" Maple 24.60' 5" Maple 12.00' B" Maple 25.46' | ing a |
| B. Description of corner evidence found and/or method applies in restoring or re-establishing corner: I-12 Found a ½" rod with P.S. #20357 and P.S. #25873 cap I-13 Found 1" iron pipe | | | | |
| i-12 Found a ½ fod w | Rn P.S. #20357 and P.S. #25 | i873 cap I-13 Found ^a | 1" iron pipe | |
| C. Description of monum | | | cating the position of the corner: | |
| Wit: *8" Maple | N54°E 8.61' | l-13 Found 1 Wit: | 44011 | 3.32' |
| *4" Maple | S17°E 13.10' | * 4151 | | 5.3∠ :4.51' |
| *6" Maple | S73°W 26.78' | | *18" Maple N78°W 1 | 9.36' |
| *6" Maple 1 ¾" iron pij | N62°W 27.01' | | | 5.43' |
| Old Fence E | ast & West | | *Old witnesses by others | ч. |
| | of trail Roads | | JE OF MIC | HIGA |
| | & East, West East 150'± ses by others | : | CARL | A A |
| | aca ny outets | | A KIISKIL | |
| Signed by: | I TKuskila | Date: | 4-16-02 LAND SURVEYO |)R |
| Surveyor's Michigan L | icense No.: 33981 | | 33981 | |
| | • | | Joseph Cano | SURVE |