

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Antrim (County)	Located In	Corner Code #
1. Public Land Survey	T <u>29N</u> R <u>6W</u>	<u>K-10</u>
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on October 24, 2000 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26	●	25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

K-10 G.L.O. H. Brevoort and J.H. Mullet D.S. 1839
 Set quarter section post
 Wit: Lynn 10 N69°W 28 Links
 Sugar 16 N52°E 32 Links

L.2 P. 74 Beryl M. Jones L.L.S. #23514 L.C.R.C. Sept. 1981
 Found "T" iron Wit: S06°E Twin Maple 64.95', S83°W Bass
 clump 49.60', N26°W 10 White Pine (no dist)

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

K-10 Found 1" iron pipe fitting Beryl M. Jones L.L.S. #23514
 distances North and South.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-10 Found 1" iron pipe
 Wit: *10" Triple Maple S06°E 66.84'
 24" Maple S47°E 85.41'
 Power Pole S36°E 27.20'
 *14" Maple S54°W 61.24'
 Centerline of North-South Road East 4'±

*Old witnesses by others



Signed by: Carl T. Kiiskila

Date: 4-16-02

Surveyor's Michigan License No.: 33981