

FEB 18 1999

158

Liber 00003 Page 0020

ANTRIM COUNTY MI.
Register of Deeds
Recorded

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

12-15-1998 10:16:13

Manda R. Conway
REGISTER OF DEEDS

For corners in

MILTON

<u>Antrim</u> (County)	Located In:	Corner Code #
1. Public Land Survey Sec. 35	T29N R 9W	K-12
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Terry B. Smith, in a field survey on 12-10-98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

G10 set post circa 1853
County Surveyor's records circa 1901
certificate R. Findorff 1965
certificate A. Lennox 1976
certificate N. Way 1997

Ratified by peer group
in accordance with
P.O. 345
Antrim Co. Chairman

Arthur L. Lennox
Arthur L. Lennox
Nov. 18, 1998

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" steel bar in road & school house per county surveyor's notes

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-12 set Antrim county monument in highway box
center line road -- East 4 ft.
UP N45E 53.00
UP N80W 27.95
UP S50W 53.25
NE Cor. House S40E 75.60



Signed by Terry B. Smith
Surveyor's Michigan License No. 25873

Date DEC. 14, 1998