

REMONUMENTATION

FEB 22 1996

COMMISSION

ANTRIM COUNTY
RECEIVED FOR RECORD

DEC 6 9 22 AM '95

Wanda R Conway
REGISTER OF DEEDS

STAR
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
ANTRIM
(County)

	Located In:	Corner Code #
1. Public Land Survey	T <u>30N</u> R <u>5W</u>	<u>F-5</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	13		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, NEIL L. WAY, in a field survey on NOV. 8, 19 95, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
F-5

GLO SET POST JULY 1839
MARKED HEMLOCK 20 FOR CORNER

LENNOX #20357 SET 1\2" IRON PIPE AT MID POINT AND ON LINE 4\11\1979

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
F-5

FOUND 1\2" IRON PIPE AND CAP LENNOX #20357.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
F-5

SET BERSTEN MONUMENT WITH CAP WITH 1\2" IRON BELOW.

Ratified by Peer Group	N59W 20.10' MPL 10 CLUMP
in accordance with	N17E 12.10' MPL 8 CLUMP
P.O. 345:	N54E 12.30' MPL 12 CLUMP
Chairman <i>Arthur L. Lennox</i>	S07W 25.30' CHERRY 4
Arthur L. Lennox	
Date: Oct. 26, 1995	



Signed by *Neil L. Way* Date 12-1-1995
Surveyor's Michigan License No. 28432

002 283