LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF–:	LOCATED IN–:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 30 N., R. 6 W.	E-9; F-9; G-8; G-9
2. PROPERTY CONTROLLING IN SECTION 21	T. 30 N., R. 6 W.	7
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on July 11, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on , 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. continued

G-9

Fd. 4" Rd. Conc. Mont. & added Ced. Post w/Loc. Tag.

8" Maple (clump)	S36°W	15.08
11" Beech	S75°W	4.06
18" Beech	N17°E	9.29
6" Maple	N40°W	37.0

7

Drove 5/8"X40" re-rod w/RLS cap and ced. post w/Loc. Tag.

8" Maple	N69°E	13.2
12" Maple	N27°W	28.7
8" Maple	S50°W	22.5
N-S fn.	Due E	20'±

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

E-9 Accepted Iron in Mon. Box as fd. & accepted by R.L.S., R.Findorff in 1969. Box is in Ctr. of E-W B.Top rd., and in line with ctr. trail rd. to South and driveway to North.

F-9 Fd. 5/8" re-rod in B.Top Rd. Fits furvey of Sec. 28, by RLS, Bob Findorff, 1969.

G-8 Fd. 3/4"X42" pipe by old corner fence post (down), fence remains E. & S.

G-9 Fd. Conc. Mon. by R.L.S. Bob Findorff, 1969.

7 Set 1/8 Cor. per STandard B.L.M. Instructions.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-9

Fd. 1" Pipe in Mont. Box.

8" Maple	S60°E	81.03
16" Maple	S40°W	60.95

Ctr. of E-W B. Top Rd.
Ctr. of Trail Rd. S'ly and Drive way N.

F-9

Fd. 5/8" Re-rod.

P.Pole	S69°E	65.40
16" Cedar	S11°W	64.62
9" Cedar	S34°W	79.13

Cedar Post w/Loc. Tag Due N 33'
Ctr. E-W B.Top Rd. in Curve Due N 3'±

G-8

Fd. 3/4" Pipe. replaced w/D.N.R. Mont. & Ced. Post.

10" Maple	S14°W	8.7
6" Maple	S70°W	16.5
9" Ir.Wood	N13°W	19.17

SIGNED BY Carl F. Roser 6-6-79 DATE

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

CHESTONIA TOWNSHIP
ANTRIM COUNTY

SURVEYOR'S MICHIGAN REGISTRATION NO.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET