

**SURVEY &
REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE**

APR 26 1995 FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

COMMISSION

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY <u>29</u> T. <u>30</u> N. S. R. <u>7</u> -E- W.		<u>D-9</u>
2. PROPERTY CONTROLLING IN SECTION _____, T. _____, N. S., R. _____ E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION _____, T. _____, N. S., R. _____ E. W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

ANTRIM COUNTY
MICHIGAN
RECEIVED FOR RECORD
DEC 5 2 04 PM '94
Wanda R. Combs
REGISTER OF DEEDS
REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Terry B. Smith, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on NOV. 22, 1994, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on NOV. 22, 1994, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

GL0 Corner Post Oct. 1855
County Surveyors notes 1888 Fredrick Church
Cedar Stake
No evidence found

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

$\frac{1}{2}$ " iron bar per surveys
found $\frac{1}{2}$ " iron rod approx. 20" below road surface when setting
monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-9 -- N $\frac{1}{2}$ Corner Sec. 29, T30N, R7W
Peer group approval Oct. 6, 1994
Set antrim County Monument and monument box
 $\frac{1}{2}$ " iron bar South 33.00
8" Tamarac S30°W 34.20
12" Basswood North 52.10
Utility Pole N50°E 47.50

Ratified by Peer Group
in accordance with P.A. 345
Chairman Arthur L. Lennox
Arthur L. Lennox
Date: Oct. 6, 1994


SIGNED BY Terry B. Smith DATE NOV. 30, 1994

SURVEYOR'S MICHIGAN REGISTRATION NO. 25873

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR



SURVEYOR'S MICHIGAN REGISTRATION NO. 002 224