

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

ANTRIM COUNTY  
 RECEIVED FOR RECORD  
 NOV 30 3 47 PM '94  
 REGISTER OF DEEDS  
*Wanda R. Combs*

For corners in

ANTRIM

(County)

Located In: SEC 21 Corner Code #

- |                                    |   |     |   |    |     |
|------------------------------------|---|-----|---|----|-----|
| 1. Public Land Survey              | T | 30N | R | 7W | G-8 |
|                                    | T |     | R |    |     |
|                                    | T |     | R |    |     |
|                                    | T |     | R |    |     |
| 2. Property Controlling in Section | S |     | R |    |     |
|                                    | S |     | R |    |     |
| 3. Miscellaneous Property in Sec.  | S |     | R |    |     |
|                                    | S |     | R |    |     |

**SURVEY & REMONUMENTATION**

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_ SECTION \_\_\_\_\_

| A  | B  | C  | D  | E  | F  | G  | H | I | J | K | L | M |
|----|----|----|----|----|----|----|---|---|---|---|---|---|
| 2  | 6  | 5  | 4  | 3  | 2  | 1  |   |   |   |   |   |   |
| 3  |    |    |    |    |    |    |   |   |   |   |   |   |
| 4  | 7  | 8  | 9  | 10 | 11 | 12 |   |   |   |   |   |   |
| 5  |    |    |    |    |    |    |   |   |   |   |   |   |
| 6  | 18 | 17 | 16 | 15 | 14 | 13 |   |   |   |   |   |   |
| 7  |    |    |    |    |    |    |   |   |   |   |   |   |
| 8  | 19 | 20 | 21 | 22 | 23 | 24 |   |   |   |   |   |   |
| 9  |    |    |    |    |    |    |   |   |   |   |   |   |
| 10 | 30 | 29 | 28 | 27 | 26 | 25 |   |   |   |   |   |   |
| 11 |    |    |    |    |    |    |   |   |   |   |   |   |
| 12 | 31 | 32 | 33 | 34 | 35 | 36 |   |   |   |   |   |   |
| 13 |    |    |    |    |    |    |   |   |   |   |   |   |

I, NEIL L. WAY, in a field survey on OCT 5, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

G-8  
 GLO SET CORNER POST OCT 1855  
 HEMLOCK 20 N51E 23  
 SUGAR 24 S54W 32

NO EVIDENCE FOUND

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-8  
 FOUND 1" IRON PIPE SET IN CONCRETE

Ratified by Peer Group  
 in accordance with P.A. 345  
 Chairman *Arthur L. Lennox*  
 Date: Oct. 6, 1994

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-8  
 SET COUNTY MONUMENT AT COR., LEANED IRON PIPE IN CONCRETE  
 S85E 17.77' MPL 6"  
 N38W 10.60' MPL 4"  
 N81W 26.10' MPL 8"  
 S24E 20.72' MPL 24"



Signed by NEIL L. WAY *Neil L. Way* Date NOV 21, 1994  
 Surveyor's Michigan License No. 28432

LRLS 002 202