

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in

ANTRIM  
 (County)

Located In: SEC 21 Corner Code #

- |                                    |   |            |   |           |            |
|------------------------------------|---|------------|---|-----------|------------|
| 1. Public Land Survey              | T | <u>30N</u> | R | <u>7W</u> | <u>G-9</u> |
|                                    | T |            | R |           |            |
|                                    | T |            | R |           |            |
|                                    | T |            | R |           |            |
| 2. Property Controlling in Section | S |            | R |           |            |
|                                    | S |            | R |           |            |
| 3. Miscellaneous Property in Sec.  | S |            | R |           |            |
|                                    | S |            | R |           |            |

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_ SECTION \_\_\_\_\_

ANTRIM COUNTY  
 RECEIVED FOR RECORD  
 NOV 30 3 55 PM '94  
 U.S. R. County  
 REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, NEIL L. WAY, in a field survey on OCT 5, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

G-9  
 GLO SET CORNER POST OCT 1855  
 CEDAR 18 N65W 48  
 CEDAR 10 S42E 17

NO EVIDENCE FOUND

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-9  
 FOUND 1/2" IRON AND CAP #12026 OSTLING AT N BANK STREAM AND 20' EAST OF N-S TRAIL

Ratified by Peer Group  
 in accordance with P.A. 345  
 Chairman *Arthur L. Lennox*  
 Arthur L. Lennox  
 Date: Oct. 6, 1994

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-9  
 SET COUNTY MONUMENT  
 WEST 3.25' HEMLOCK 6"  
 N28W 11.88' CEDAR 8"  
 N39E 9.76' HEMLOCK 6"  
 N83E 7.14' CEDAR 8"  
 S08E 21.88' HEMLOCK 8"



Signed by NEIL L. WAY *Neil L. Way* Date NOV 21, 1994  
 Surveyor's Michigan License No. 28432