LAND CORNER RECORDATION CERTIFICATE		. %	-	4			13 ( ) 1 ( )	るませ			
Filing Requirement of Act 74, Mich. P.A. 197	U (3) (3) (3)		GISTER			10 mg/s			3	≥ ¢ e.	
NOTRIM Located In: SEC24 Corner Code =##			3	1		_D		96	50		
(County)		7.5	유	Ş		6	19 s.	71 2	~ _	0.00	
Dublic Land Survey	Silver of Silver		DEEUS		1996 <b>E</b> rrie	∳. ∸ ⊘. ⊐	2	ECORD	الله أ	<b>ં</b>	
Tubile Land Sulvey	37		2		l 🗀		É	ž	-	ς,	
$oxed{F}_{\mathbf{r}}$			U	) <b>(</b>				_		in all	
	Sign for				ું જેલ	10 m					
Property Controlling S T R			- 14						, . e.	Š	
in Section S T R		. ".	*	3 48	7457 8783	K MANY Longraphy	r i i jeri Rođe	٠.			
	egister	of D	eed:	s St	amr	. & I	File	Nur	nber	: در ا	
Property in Sec. S T R			1,00	d se	. K.		<u> </u>	-		3	
		. 7.7		20,637	Ng S	į.Α.			40	, ·	
. Lot No Recorded Plat	_ A	В	C I	) É	F	G	н	i j	κ.	Ĺ	
. Private Claims	-			. J. 9	4 P	× 45 ·	$T_{i}$		324		
<u> - '^ </u>	- 1	- 6	1	7 5 7			3 <u>—</u> 	1 1		7	
- 즐물레이 사람들의 이번 바닷컴을 받는 사람이 있는 다시 다시 다시 다시다.	1	T	1.	- 13 B					7	<u>.</u> S.	
NEIL L. WAY , in a field survey on OCT 5, 1994 , 19,		- 7 <del>-`-</del> .   ::^.	1 8   ·-	30	— e <u>—</u> ∴ ∴	<u> </u>	10-		1		
o hereby certify that under requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned	<u> </u>	+				1 %		$\Box$		_	
n lines 1 and 2 above were in conformance with regulations and rules therefore as required in the	- 5 <del>-</del>	-1 <del>8</del>	17		-16-	3 2	15-	111	1	<u>-</u> 1	
urrent manual of survey instructions of the United States Department of the Interior, Bureau of Land	'' ' <u> </u>	+-		+		1 150	+	H		-	
anagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 bove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a	8	-19	20	1	-21 <u>-</u>	1.	22	23	3—	-:	
ourt of Law; established, re-established, monumented, re-monumented, recovered, found as	9 -			3	<del>-  -</del>	+	+	1		- <u>-</u>	
kpressed below:	10	30—	29	\ .	28	+-	27	-26	<del>}  </del>	-2	
OTE: Not more than 4 corners, all in the same town and range, may be recorded	11		$\vdash$	3.2	+	+	1		-		
on this certificate.	12	31	—3 <sup>2</sup>		-33	+	34—	<del>  3</del> 5	,- -	-3	
	13		Щ.			1	<u> </u>	ا ا		Ţ	
. Description of original monument and accessories and/or subsequent restoration:									원인	\ 	
			ź						28	2.	

no evidence found

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND BUGGY AXEL

GLO SET COR POST OCT 1855

SUGAR 8 S42W 29 BEECH 10 N29W 34

> Ratiffied by Peer Group in accordance with P.A. 34

Arthur L. Lennox Datc: Oct. 6, 1994

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET COUNTY MONUMENT

N09W 27.98' MPL 8" S79W 19.65' BEECH 36"

S67E 13.50 MPL 14" N88W 37.32 MPL 14"

Signed by NEIL L. WAY

Surveyor's Michigan License No. 28432

Date NOV

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983