STATE OF MICHIGAN DEPARTMENT 0F NATURAL RESOURCES

LAND CORNER RECORD

		ANTRIN	COUNTY
		1 <u>37 R</u>	R
DESCRIPTION OF CORNER	ME corner of Section	8	
CORNER MONUMENT	Set DAR menument		
DATE MONUMENT PLACED AND WI	TNESSED		
WITNESSES TO CORNER	4" Naple	и 6 Е	7.01
N -	7" Maple tw.		29.61
1 2	7" Maple twin	S 61 E	50.41
,	ND E-W Trail road	Due \$	95'
CIRCLE CORNER REGISTERED			SECTORED.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner reestablished at double the distance of a line projected through the H 1/4 councy of Sec. 2 and the E 1/16 corner on the M line of Section 2, this being an eld E-W fence remains with eld fence corner at E 1/18.

A 1/14 corner positioned by this method fits the U.S. tie South to stream crossing within less than 10' (638'-Hea.). Occupancy (old fence) was accepted on the N line of the HE 1/4 of Sec 2, since there is a record of survey activity along this line, dated 1884 and 1885; see ald County Surveyor's Book 8 & C-302 at Charlefoix County Register of Deeds.

SURVEYOR'S SEAD CO LAND SURLING

DISTRIBUTION:

REGISTERED LAND SURVEYOR 12028

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68