STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		T	<u>, n</u> R , S H	
DESCRIPTION OF CORNER	S 1/4 corner, Sec.	10		
CORNER MONUMENT	lk" pipe, added Cod	er post w/locati	on tag	
DATE MONUMENT PLACED AND	WITNESSED	.0-26-71	-	
WITNESSES TO CORNER	. S" twin Haple	N 18 E	139.7'	
	7" Hemlock	N 70 W	231.4	
1	20" Beech	8 27 W	172.61	
	AND			
CIRCLE CORNER REGISTER	ÆD			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Recovered 1k" pipe as established by M.S.H.D. by single proportion in 1962.

CATL 1. DOM

SURVEYOR'S SEAL

SIGNED DA

11-4-71

ANTRIN

COUNTY

DISTRIBUTION:

REGISTERED LAND SURVEYOR18028

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing