## STATE OF MICHIGAN DEPARTMENT 0F NATURAL RESOURCES

## I AND CORNER RECORD

			ANTRIN	COUNTY
			T 31 N R	<u> </u>
DESCRIPTION OF CORNER	NV (	permer, Section 5		
CORNER MONUMENT	Set	DKR Nonument		
DATE MONUMENT PLACED AND WI	TNESSED	11-10	-71	
WITNESSES TO CORNER	12"	Heple	<u> </u>	82.2!
N <sup>q</sup> -	9"	Maple	н о Е	26.7
		Maple	8 13 E	36.4 <sup>1</sup>
	<b>N</b> D	Yence Remains Overgrown N-S Rd.	Due E Grade Due W.	12'
CIRCLE CORNER REGISTERED			Due S	12.71
DESCRIPTION IN DETAIL AS TO			ND IDENTIFIED OR RES	STORED.

Corner reestablished about one rod West of, and parallel to, eld fence remains South, and on straight line between section corners 1/2 mile West and two miles East, which is very close to a corner by proportionate measure E and W. The Southerly end of the fence South appears to be a 20% fence near East side of County Road about a 1/4 mile North of SW corner of Sec. 5. The old road grade some 12 ft.

West of the MW corner of Section 5 was built prior to 1887 and was probably not built on the N-S Sec. line, according to Henry Korthase.

SURVEYOR'S SEAL

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing