REMONUMENTATION

FEB 1 1 1998

Property in Sec.

ANTRIM COUNTY MI.

1.50		V 1	
ND CORNER RECORDATION CERTIFICAT	ecorded		

For corners in SECTION		Filing Requirement of Act 74, Mich. P.A. 1970					
ANTRIM (County)	Located in:	Corner Code #	ZAKE	Wanda R. Conway REGISTER OF DEEDS			
1. Public Land Survey	17 T3/N	R <u>8W &-6</u> R	<u>-</u>				
Property Controlling in Section Miscellaneous	S TI S TI S TI	R					

, Recorded Plat 5. Private Claims

in a field survey on 12-01 I, Terry B. Smith, in a field survey on 12-01, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1 A B	C I	ЭЕ	F (3 H	1 1	JΚ	L
2 - 6		5	- 4		,	2	.l_
3	_	<u> </u>					\perp
4 - 7-	-	B — —	- - 	1	ò——:	111	 1 <u>2</u> -
5		- -					-
6 -18	1	7-	 -16	1;	5	 4	 13—
7		-					₋
819-	2	<u> </u>	-21		2;	3	 24—
ا ا و		_				ļ ļ. <u> </u>	_
10-30-	2	9	 -28	 2	72	6	 ?5—
11	_			\Box	<u> </u>		_
12 31-	3	2	.33	3	43	 5;	 36
13							

Register of Deeds Stamp & File Number 127

A. Description of original monument and accessories and/or subsequent restoration:

GLO Corner -- 3½" Ironwood Post midway and online at 40 chains Beech 7. N27E 13L Beech 17. S55W 58

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Plat of PARADISE HILLS Survey by Lennox & Assoc. 1997 Survey by R. Dunn, 1973 Survey by C. Ostling 1973 LCRC Liber 205 page 478 -- 1973

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner;

Found ½" bar & set Antrim county Monument 36" Maple S28°20'W 51.40 U.P. S78°40'E 35.50 U.P. \$48°E 79.30 iron bar East 33.00

Ratified by Peer Group in accordance with P.A. 345 Antrim Co-Chairman

Arthur L. Lennox Nov. 18, 1997

Signed by ___ Date SERITM 25873 LAND SURVEYOR

> EDED LAND S CONTRACTOR OF THE PROPERTY OF

REVISED MAY 14,1975

Surveyor's Michigan License No.

'nĐ. 25873