APR 06 1999

SECTION

ARENAC COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in			1								
AREN		Located In:	Corner Code Rose Smil	1. H				LC		2/ 17	'1 P
(Coun	nty)		AREN RS Rec.	IAC C	00,	REC	9. 0	F D		10±5	: •
1. Public Land S	iurvey	T <u>18N</u> R <u>4E</u>	<u> </u>	FEE	S:	./ (77 IZCI	1	. Ame	9.0	
		TR	····								
		TR T R									
2. Property Cont	trolling S	TR									
in Section	s	TR									
Miscellaneous Property in Se		TR									
i roporty in de	<u> </u>	'			Regi	ster o	of Dee	ds Sta	mp & i	File Numi	ber
4. Lot No	, Recorded Pla	at									
				1	A B	C _	D E	FG	H I	JK	L M
				2	6-		\$ 	- 4		<u> </u>	-
I, DALE L. WIN		in a field survey on	NOVEMBER 6 , 19 98 do hereb	y 3	\vdash				+		+
state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the							8	- 9	-10	-1/1	-12
current manual of survey instructions of the United States Department of the Interior, Bureau of Land								+ +	\dashv		+
Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a							7-	-16	-1/5	—1/4—— ····	-1.3-
Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed						+	 	- 			
below;				8	1'9_ i			-21	-22-	-23	-24
		he same town and rang	e, may be recorded	9		+		╁	1-1		
on this cert	tificate.			10	30- 	+-	29 <u> </u>	-28	-27	-26	-2°5
				11		Τ.					
A. Description of	f original monument	and accessories and	or subsequent restoration:	12	1 1			3.3	_34		36
	, original mortalities	una accessories and	ioi subsequent restoration.								
HEMLOCK 26"	T SET IN JULY 1843 S 73° E 21 LKS. N 43° W 11 LKS.	BY J. BURT, D.S.									
2. LCRC, L.1, P.18	88, N. CALDWELL, PS	#12018, (1964) SET	1/2" PIPE AND 1/2" BAR IN PAVEN	MENT F	ROM (COUN	TY SU	RVEY I	RECOR	DS	
3. LCRC, L.2, P.10	00, S. KOCH, PS #41	103, (1997) FOUND ½	BAR IN PAVEMENT								
B. Description o	f corner evidence fo	ound and/or method a	pplied in restoring or reestablish	ning co	mer:						
I-8 SEARCHED AT THE	APPARENT LOCATIO	N OF THE CORNER AN	D FOUND A 1/2" PIPE IN PAVEMEI	NT. FXC	CAVA	TED C	ORNE	RAND	FOLIMI	O NO OTH	1ED
OBJECTS.			(ER 60.60' (R) 60.45' (M); S65°W								
SOUTHWEST CORN	ER OF RESTAURANT	FOUNDATION 181.15	(R) 181.15' (M) NOTE: BUILDING I	S NOW	A HO	USE;	58.58 EAST	OF WE	STEDO	И); N35°E SE OF	: 10
CHECKED WITNESS	ES FROM L.2, P.100 /	F ROAD WEST 15.2' (F ALL MEASUREMENTS ' ABLE EVIDENCE OF TH	R&M), WERE IDENTICAL TO THE RECORD IE POSITION OF THE ORIGINAL CO	NFOR	MATIC	ON.					
C. Description of	monument for corn	er and accessories e	stablished to perpetuate locating	g the p	ositio	n of 1	he co	rner:			
⊦ 8										attespe.	•
REPLACED 1/2" PIPE	IN PAVEMENT WITH	5/8" REBAR WITH AR	ENAC COUNTY REMONUMENTATI	ON CAF	PINM	IONUI	MENT	вохи	SE OF	MICHIG	a de la companya de l
N 60°W 57.00° EAST 64.17' TO S 65°W 58.43'	O NAIL AND TAG II O NAIL AND TAG II TO NAIL AND TAG II	N NORTHEAST SIDE OF JORTH SIDE OF 20" PC N TOP OF CONCRETE F	ENAC COUNTY REMONUMENTATI F POWER POLE PLAR R/W MARKER				*		DA WIN	LE L. IECKE	
EAST 9.00' TO	THE PHYSICAL CENT	ERLINE OF M-13	V				- ₹	5	PROFE		. 8
SOUTH 2.20' TO SEAPE 11 09' TO	O THE PHYSICAL CENT	NTERLINE BERNTHAL R TAG USED FOR AERIAL	OAD				T	T C	_	VEYOR No.	T X
EAST 15.20' TO	O THE WEST EDGE OF	PAVEMENT IN THE C	ENTERLINE OF BERNTHAL ROAD T	O THE	WEST		3	$\sim 60^{\circ}$.	41	915	83
Signed by	Dale Win	* ,		Date _		12/	16/3	182	OFES	SIONA	A LONG TO LE VON
Surveyor's Michig	gan License No	41915				,			-7444	+++++	
FB. 2, P. 87			Eggs Angelia	h hv 182-	4041 -	****					

IVEYORS, JAN. 28, 1971 REVISED MAY 14, 1976 REVISED JAN., 1983