## LAND CORNER RECORDATION CERTIFICATE

|  | Filing Requiremen   | t of Act 74, Mich. PA 1970   |
|--|---|--|
| For Corners In: Arenac (County)  | Located In Corn   | er Code #  |
| 1. Public Land Survey 2. Property Controlling in Section 3. Miscellaneous Property in Section 4. Lot No: 5. Private Claims: 1, Craiq W. McVean, in a firequirements of PA 74, Mic and 2 above were in conforthe current manual of sur Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board of established, re-established, | T R T R T R S 8 T 19N R 3E 1 S 8 T 19N R 3E 1 S 7 R S T R S | Register of Deeds Stamp & File Number  A B C D E F G H J J K L M  2 - 6 - 5 - 4 - 3 - 2 - 1 - 3  atte that under ned in lines 1 as required in riment of the and/or that the with the rules rount of Law; d below:  B C D E F G H J J K L M  1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1   |
| A. Description of original  11 - None  | monument and accessories and/or subs  | sequent restoration:  12 - None  CRAIG W. MCVEAN PROFESSIONAL SURVEYOR No. 39088   |
| 11 – SW 1/16 Cor., Sec<br>Set 2" Alum. Cap o<br>procedure. Fence   | evidence found and/or method applied in , 8 - n 5/8" x 34" rebar per Standard BLM to E. is 22'± N. Fence to S. is 55'± W. ugh trees to E & S is 14'± NW.  | n restoring or re-establishing corner:  12 – CS 1/16, Cor., Sec. 8 - Set 5/8" x 48" rebar with stamped 2" Alum. Cap per BLM procedure. E-W fence is 39' N. Centerline E-W ditch is 22' N.  |
| 11 – Set 2" Alum. Cap of<br>N20°W 5.80' to set<br>N48°E 7.95' to set I<br>S02°E 11.93' to set<br>S58°W 13.04' to se  |   | ied to perpetuate locating the position of the corner:  12 - Set 5/8" x 48" rebar with stamped 2" Alum. Cap N57°W 73.12' to set N & T in NE. side 9" B. Cherry Set Blue Carsonite Post with loc. tag 1' N N11°E 41.88' to set N & T in W. side 8" B. Cherry N47°E 55.27' to set N & T in SE side 12" Oak S8°W 26.21' to set ½" x 23" rebar |
| Signed by: Ome W. M. Ven Date: 11/30/2005  Surveyor's Michigan License No.: 39088  |   |  |