LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY 36	T. 20 N., R. 3 E.	K-13; L-13; M-13
2. PROPERTY CONTROLLING IN SECTION 36	T. 20 N., R. 3 E.	16
3. MISCELLANEOUS PROPERTY IN SECTION ____	T. ____ N. S., R. ____ E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER _____

I, KENNETH J. OSTLING, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on FEBRUARY 23, ____, 1982, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX

C. (CONTINUED)

16
SET 5/8" X 36" IRON BAR W/RLS CAP
9" TRI. R. MAPLE S43°W 19.'
4" W. PINE N75°E 40.8'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

K-13 FOUND 1" PIPE AT CORNER WHICH APPARENTLY PERPETUATES CORNER FOUND IN HALLISTER (1910) SURVEY OF TOWN LINE. FITS OCCUPATION AND APPEARS ACCEPTABLE AS CORNER.

L-13 SET BY SINGLE PROPORATION MEASUREMENTS BETWEEN SECTION CORNERS COULD LOCATE NO PREVIOUS CORNER.

16 SET CORNER BY STANDARD SURVEY PROCEUDRE FOR SUBDIVISION OF SECTIONS.

M-13 SET ON LINE DOUBLE DISTANCE OVER FOUND 1/4 AND SECTION CORNER NORTH. NOTHING EVIDENT FOR CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-13
SET DNR MONUMENT AT PIPE
14" CHERRY N17°W 55.9'
4" W. PINE N75°E 69.5'
NW COR. SEC. 1 S89°30'38"E 12.54'
719NR3E

L-13
DNR MONUMENT
6" R. MAPLE N50°E 21.0'
6" R. MAPLE N27°W 21.7'

M-13
SET DNR MONUMENT
5" R. MAPLE N57°W 23.0'
18" B. OAK S70°E 16.1'
BOTTOM OF RAVINE, WNW-ESE, 25' SOUTH OF CORNER

STATE OF MICHIGAN
KENNETH J. OSTLING
LAND SURVEYOR
No. 10068
(SEAL)
REGISTERED LAND SURVEYOR

SIGNED BY Kenneth J Ostling DATE 9-

SURVEYOR'S MICHIGAN REGISTRATION NO. #10068

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ ARENAC COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET