LAND CORNER RECORDATION CERTIFICATE † Filing Requirement of Act 74 Mich. PA 1970

			ılıng Requi	rement of F	CC 74, MICI	1. PA 13 	310					
For Corners In: Arenac (County)		Locate	d In	Corner Co	ode#							
1. Public Land Survey		T 20N	R 3E	D7								
Property Controlling in Section	s	' —— -	R									
Miscellaneous Property in Section	ss	- ' - T - T					Renis	ter of De	eds Sta	ımo & Fi	ile Num	her
4. Lot No:	Recorde											
5. Private Claims:						1 A	BCI		GF		K L	. <u>M</u>
I, Craig W. McVean, in a firequirements of PA 74, Mic and 2 above were in conformation the current manual of surfinterior, Bureau of Land Ma corner points mentioned in of the Michigan Board of established, re-established, NOTE: Not more than be recorded on this certain the conformation of the Michigan Board of established, re-established, the recorded on this certain the conformation of the michigan Board of established, re-established, the recorded on this certain the conformation of the michigan Board of the michigan Boa	chigan PA rmance wit vey instruct nagement lines 3, 4 a Land Sui monumen 2 corners	of 1970, the regulations of the or by a decre and 5 above viveyors or bited, recovere	corner points and rules the United State e of a Court of vere in confo y a Decree d, found as e	mentioned in erefore as req es Department of Law and/or rmance with the of a Court of expressed before	lines 1 uired in t of the that the ne rules of Law; w:	3 — 4 — 5 — 6 — 7 —	-7 8	7 16		j1,	1	3
A. Description of original D7 – GLO – Set ½ Post W. Pine 10" N26°E Maple 6" S45°W 8 – CSR – L. 1, p. 34 – W. Pine St. S36½° 39.87 CH. To 'C7' – MDOT Wit. Card – (LCRC – L. 1, p. 24 Fd. 1" pipe (flush), Fence post N25°E		uent restoration: Cor. Fn. Post Due S. 28.67' - CPC – Drawing #SF 16944 – Sheet 94 – 1968 Corner set - Rec. Sur. – L. 1, p. 462 – L. D. McGinnis – 1981 – Fd. 5/8" iron in Mon. Box. Same Wit's as MDOT LCRC – L. 3, p. 75 – D. L. Winiecke – 2004 – Fd. ½" iron in Mon. Box. South 28.50' to a nail and tag in Fence post; S20°E 31.40' to a nail & tag in fence post; N60°E 68.18' top centerline of Verizon Cable Marker Post; North 111.92' to a PK nail and tag in fence post.										
B. Description of corner	evidence :	found and/o	r method ap	oplied in rest	oring or re-e	stablishi	ing corn	er:				
D7 – ¼ Corner common dimensions E & W a of N-S Sand Drive i	and two M	ADOT wits.	Centerline o	of rerouted B	it. Rd. on cu	rve is N	NW 55' a	and fen	ce line	south	& norti	h. Centerlin
C. Description of monum D7 – Add 3" Arenac Co. S6°E 28.45' to set S54°E 47.34' to se N17°W 121.86' to se S76°W 39.78' to se Set Orange Carsor	Remon. E N & T in V t N & T in set N & T et 3/8" x 18	Brass Cap o W. side RR I NE side RR in E side 6" 8" rebar	n Fd. 5/8" in Tie corner p I Tie post (N	on rod in Mo ost (MDOT, MDOT)	n. Box.	locating	the pos	ition of	To * LICENSE	CRAMC!	/E YOR O. 188	Tr.
Surveyor's Michigan L	icense N	o.: :	39088			4	1 22	, <u>, , , , , , , , , , , , , , , , , , </u>				