LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF–:	LOCATED IN–:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 20 N., R. 5 E.	G-7; H-7
2. PROPERTY CONTROLLING IN SECTION 22	,T. 20 N., R. 5 E.	1; 2
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Kenneth J. Ostling, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on December 19, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

G-7 Set corner at old fence corner (N & W) which seems the best available evidence. Resident in Sec. 16 claims to have helped reconstruct fence which was reportedly located according to a "survey". Seems to be located as much as 90' too far S but can find no good evidence at porportionate location. No record of corner being estab. in 1911 survey of record, as were other corners in Sec. 22.

H-7 Set corner from probable NBT's of record in 1911 survey. Fits good for measurements of record in Sec. 22. Pine stump SE and remains SW.

1 Set by standard survey procedure for subdivision of sections.

2 Set corner by standard survey procedure for subdivision of sections.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-7

Set DNR mon. & cedar post

6" W. Pine	S10°W	29.6
6" W. Pine	S83°W	22.2

H-7

Set DNR mon. & cedar post

8" R. Pine	N41°W	31.3
5" R. Pine	N65°E	37.85

1

Set 5/8"x40" bar w/cap and cedar post

4" W. Pine	N29°W	22.35
3" W. Pine	S57°W	33.45

2

Set 5/8"x40" bar w/cap & cedar post

3" W. Pine	N47°E	12.45
3" W. Pine	S16°E	13.8

STATE OF MICHIGAN KENNETH J. OSTLING LAND SURVEYOR No. 10068 REGISTERED LAND SURVEYOR

SIGNED BY Kenneth J Ostling DATE 1-6-78

SURVEYOR'S MICHIGAN REGISTRATION NO. 10068

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ ARENAC COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET