

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. 20 N. R. 5 E.	F-8; F-9
2. PROPERTY CONTROLLING IN SECTION _____	21 T. 20 N. R. 5 E.	9
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. R. _____ E. S. R. _____ W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Kenneth J. Ostling, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on February 3, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:


A. Description of original monument and accessories and/or subsequent restoration:

- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- 8 Set corner at calculated intersection of true 1/4 lines according to standard survey procedure. F'11s in center N-S So. road, about 10' N of center of road west.
 - 9 Found 1/2" iron bar in center of N-S-E-W roads.
 - 9 Set by standard survey procedure for the subdivision of sections.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-8	F-9	9
Set PK Nail in Blacktop	Left 1/2" Iron Bar in Place	Set 5/8" Rod w/R.L.S. Cap
Nail in Cor. Fence Post	Nail in PP N50°W 49.7	10" W. Pine S26°W 19.8
S55°W 48.85	Nail in Cor. Fence Post	6" Maple N81°W 13.3
Nail in PP N24°W 72.53	N48°E 51.5	

SIGNED BY *Kenneth J. Ostling* DATE 8/2/78
 SURVEYOR'S MICHIGAN REGISTRATION NO. 10068



FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY
 APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ ARENAC COUNTY