

# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>20</u> <sup>N.</sup> / <sub>S.</sub> , R. <u>7</u> <sup>E.</sup> / <sub>W.</sub>	<u>J-5, K-3, K-4</u>
2. PROPERTY CONTROLLING IN SECTION _____	, T. _____, N. <u>      </u> , S. <u>      </u> , R. _____, E. <u>      </u> , W. <u>      </u>	_____
3. MISCELLANEOUS PROPERTY IN SECTION _____	, T. _____, N. <u>      </u> , S. <u>      </u> , R. _____, E. <u>      </u> , W. <u>      </u>	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Kenneth J. Ostling do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on 4-23 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_ 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- J-5** Set corner 33.0' N of found 1/2" pipe, which we take to be the R/W offset stake from the 1/4 corner. Fits good for measurement between other corners.
- K-3** Found 3/4" pipe and wood stake bottom in 6" conc. tile. Accepted as corner by local residents and surveyors.
- K-4** Found 1" pipe in centerline N-S road, apparently accepted as 1/4 corner. Fits for measurement N & S.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

	J-5	K-3	K-4
1/2" Iron Bar		Set DNR mon in 6" conc. tile	Left 1" pipe, raised with cabin spike.
1/2" pipe	S 33.0'	NW cor of Bldg	N57E 92.1'
Face of P.P.	S 4 W 91.2'	4" Poplar	S62E 25.5'
			E. End 12" cor. metal culvert
			S26E 32.2'
			38" Willow clump
			N50E 35.7'


SIGNED BY Kenneth J. Ostling DATE 5-16-73

SURVEYOR'S MICHIGAN REGISTRATION NO. 10068

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
MICHIGAN REGISTERED LAND SURVEYOR



(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_