LAND CORNER RECORDATION CERTIFICATE

I week

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

L PUBLIC LAND SURVEY. T. 20. N. R. 7 & F-3, F-5, F-3 G-5 2. PROPERTY CONTROLL. N. R. W. 3. MINICELLANDOUS PROPERTY IN SECTION T. N. R. W. 3. MINICELLANDOUS PROPERTY IN SECTION T. N. R. W. 4. LOT NO. RECORDED PLAT L. Kenneth J. Ostling the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—uver) were, in a field survey on 1970, established, re-catablished, monumented, re-manuscrited, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current mount of survey instructions of the United States Department of the interior, Bureau of Land Management on by a decree of a court of law. Puthermore, that the counter points mentioned in lines 3, 4 and 3 above were in a litel survey on 19 onund, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law. A. Description of original monument and accessories and/or subsequent restoration: Set corner by proportionate measurement between section corners. B. Description of original monument and accessories and/or subsequent restoration: Set corner by proportionate measurement between section corners. Found old stake point 33' E of Fence corner & in line with £ of Road South. Found metal attraction below surface of blacktop at intersection of roads. Did not excavate but should be okay for corner. Corner set by proportionate measurement between section corners. Found 1" point a corper about 25'. North of centerline of road. Said to be the COUNTS. Found 1" point a corper about 25'. North of centerline of road. Said to be the COUNTS. Found 1" point and the properties described and properties described and properties described and properties. Found 1" point a corper about 25'. North of centerline of road. Said to be the COUNTS. Found 1" point a corper about 25'. North of centerline of road. Said to be the COUNTS. Found	FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER		
9. MINCELLANIOUS PROPERTY IN SECTION T. S. R. W. 4. LOT NO. , RECORDED PLAT 5. PRIVATE CLAIMS REPROPERTY IN SECTION T. S. R. W. 4. LOT NO. , RECORDED PLAT 6. Kenneth J. Ostling do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 3 above were, in a field survey on the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 3 above were, in a field survey on 19. To found, recovered, resorced, established or e-restablished and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law. A. Description of original monument and accessories and/or subsequent restoration: Set corner by proportionate measurement between section corners. B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Found old stake point 33' E of Fence corner & in line with L of Road South. Found metal attraction below surface of blacktop at intersection of roads. Did not excavate but should be okay for corner. Curner set by proportionate measurement between section corners. Found 1" pipe at corper about 25', North of centerline of road. Said to be the corner by pipe at corper about 25', North of centerline of road. Said to be the corner by pipe at corper about 25', North of centerline of road. Said to be the corner of the pipe and	1. PUBLIC LAND SURVEY	_ T. 20 %, R. 7 %.	E-3, E-5, F-3, G-5, F-5		
5. PRIVATE CLAIMS 1. Kenneth J. Ostling do hereby certify that under requirements of P.A.74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram envery were, in a field survey on 427-19/3, established, re-established, morumented, re-evented restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management of y a decree of a court of law. Furthermore, that the corner points mentioned in lines 3,4 and 3 above were, in a five accuracy of law. Furthermore, that the corner points mentioned in lines 3,4 and 5 above were, in a five accuracy of law. 19. found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law: A. Description of original monument and accessories and/or subsequent restoration: Set corner by proportionate measurement between section corners. Found old stake point 33' E of Fence corner & in line with L of Road South. Found metal attraction below surface of blacktop at intersection of roads. Did not excavate but should be okay for corner. Corner set by proportionate measurement between section corners. Found 1" pipe at corner about 25'. North of centerline of road. Said to be the corner by logal testingory and other survey originished to perpetuate lucating the position of the corner and securious serial subsequent properties to the position of the corner: E-5 Set DNR Monument P.K. Nail in blacktop Set DNR Monument South 2-7 Set DNR Monument South 2-7 Set DNR Monument South 3-7 Set D	2. PROPERTY CONTROLL- ING IN SECTION———	N. R. E. W.			
Set corner by proportionate measurement between section corners. A. Description of original monument and accessories and/or subsequent restorations: Set corner by proportionate measurement between section corners. B. Description of original monument and accessories and/or subsequent restorate but should be okay for corner. Corner set by proportionate measurement between section corners. Found netal attraction below surface of blacktop at intersection of roads. Did not excavate but should be okay for corner. Corner set by proportionate measurement between section corners. Found netal attraction below surface of blacktop at intersection of roads. Did not excavate but should be okay for corner. Corner set by proportionate measurement between section corners. Found 1" pipe at corner about 25', North of centerline of road. Said to be the corner by local testingony and other surveyors about 25', North of centerline of road. Said to be the corner by local testingony and other surveyors about 25', North of centerline of set DNR Monument 10" Bl. Ash N70E 20.2 Face of 6" Scht Pine S3E 49.5' 13" Maple S04W 12.7 Set DNR Monument Set DNR Monument Set 1" x30" Pipe Set DNR Monument Set 1" x30" Pipe Sign Post S SW 9.5' Cittle Party Center of NATE And South Surveyors Monument Set 1" x30" Pipe Sign Post S SW 9.5' Cittle Party Sign Post S SW 9	3. MISCELLANEOUS PROPERTY IN SECTION	.,T N. E. E			
Kenneth J. Ostling do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a 1973, established, re-established, monumented, re-monumented, re-	4. LOT NO, RECORDED PLAT				
the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) where, in a field survey on 4-27—1973, established, re-established, monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management of a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19—, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law: A. Description of original monument and accessories and/or subsequent restoration: Set corner by proportionate measurement between section corners. B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Found old stake point 33' E of Fence corner & in line with @ of Road South. Found metal attraction below surface of blacktop at intersection of roads. Did not excavate but should be okay for corner. Corner set by proportionate measurement between section corners. Found 1" pipe at corner about 25' North of conterline of road. Said to be the Corner by Droad technique of manument for forner and accessories established to perpetuate locating the position of the corner: E-3 E-4 Set DNR Monument P. K. Nail in blacktop Set DNR Monument P. K. Nail in blacktop Set DNR Monument P. K. Nail in blacktop Set DNR Monument Set DNR Monument P. K. Nail in blacktop Set DNR Monument Set DNR Monument Set DNR Monument F-5 Set DNR Monument Set DNR Monument F-6-5 Set DNR Monument F-7-5 Set DNR Monument F-7-5 Set DNR Monument F-8-7 Set DNR Monument F-9-7 Set DNR Monument F-8-7 Set DNR Monum	5. PRIVATE CLAIMS				
Set corner by proportionate measurement between section corners. B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Found old stake point 33' E of Fence corner & in line with (L of Road South.) Found metal attraction below surface of blacktop at intersection of roads. Did not excavate but should be okay for corner. Corner set by proportionate measurement between section corners. Found 1" pipe at corner about 25' North of centerline of road. Said to be the corner by local testimony and other surveyors established to perpetuate locating the position of the corner: E-3 Set DNR Monument P. K. Nail in blacktop Set DNR Monument 10" Bl. Ash N70E 20.2 Face of 6" Scth Pine S35E 49.5' 13" Maple S04W 12.7 16" Maple N15E 24.3 Face of P.P. S61W 91.6' 10" Maple S75E 16.1 G-5 Set DNR Monument Set 1"x30" Pipe 15" Poplar S77E 16.9' 8" Tw Maple S40t 76.8' Sign Post S 5W 9.5' Ctrli Pwmt S0UTH 24.1' 24.5' N of ctrli of Pvmt. in Face of Cor Fen Post S3W 54.2' 24.5' N of ctrli of Pvmt. in Face of Cor Fen Post S3W 54.2' SURVEYOR'S MICHIGAN REGISTRATION NO. 10068 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY CHIEF OF SURVEY PARTY DATE SIGNED BY DATE	the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on 4-27- 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of				
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Found old stake point 33' E of Fence corner & in line with IL of Road South. Found metal attraction below surface of blacktop at intersection of roads. Did not excavate but should be okay for corner. Corner set by proportionate measurement between section corners. Found 1" pipe at corner about 25' North of centerline of road. Said to be the corner by local testimony and other surveyor's striction of monument for both of the corner. E-3 Set DNR Monument P. K. Nail in blacktop Set DNR Monument 10" B1. Ash N70E 20.2 Face of 6" Scth Pine S35E 49.5' 13" Maple S04W 12.7 16" Maple N15E 24.3 Face of P.P. S61W 91.6' 10" Maple S75E 16.1 G-5 Set DNR Monument Set 1"x30" Pipe 15" Poplar S77E 16.9' 8" Tw Maple S40L 76.8' Sign Post S 5W 9.5' Ctrli Pvmt S0UTH 24.1' S194 Sign Post S 5W 9.5' Ctrli Pvmt S0UTH 24.1' S195 South South South SIGNED BY SURVEYOR'S MICHIGAN REGISTRATION NO. 10068 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY CHIEF OF SURVEY PARTY DATE SIGNED BY CHIEF OF SURVEY PARTY DATE SIGNED BY CHIEF OF SURVEY PARTY	A. Description of original monument and accessories and/or subsequent restoration:				
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Found old stake point 33' E of Fence corner & in line with L of Road South. Found metal attraction below surface of blacktop at intersection of roads. Did not excavate but should be okay for corner. Corner set by proportionate measurement between section corners. Found 1" pipe at corner about 25' North of centerline of road. Said to be the corner by local testimony and other surveyor's established to perpetuate locating the position of the corner: E-3 Set DNR Monument P. K. Nail in blacktop Set DNR Monument 10" B1. Ash N70E 20.2 Face of 6" Scth Pine S35E 49.5' 13" Maple S04W 12.7 16" Maple N15E 24.3 Face of P.P. S61W 91.6' 10" Maple S75E 16.1 G-5 Set DNR Monument Set 1"x30" Pipe 15" Poplar S77E 16.9' 8" TW Maple S40L 76.8' Sign Post S 5W 9.5' Ctrli Pvmt S0UTH 24.1' S1" N of ctrli of Pvmt. in Face of Cor Fen Post S3W 54.2' SURVEYOR'S MICHIGAN REGISTRATION NO. 10068 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY CHIEF OF SURVEY PARTY DATE SIGNED BY CHIEF OF SURVEY PARTY					
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Found old stake point 33' E of Fence corner & in line with L of Road South. Found metal attraction below surface of blacktop at intersection of roads. Did not excavate but should be okay for corner. Corner set by proportionate measurement between section corners. Found 1" pipe at corner about 25' North of centerline of road. Said to be the corner by local testimony and other surveyor's established to perpetuate locating the position of the corner: E-3 Set DNR Monument P. K. Nail in blacktop Set DNR Monument 10" B1. Ash N70E 20.2 Face of 6" Scth Pine S35E 49.5' 13" Maple S04W 12.7 16" Maple N15E 24.3 Face of P.P. S61W 91.6' 10" Maple S75E 16.1 G-5 Set DNR Monument Set 1"x30" Pipe 15" Poplar S77E 16.9' 8" TW Maple S40L 76.8' Sign Post S 5W 9.5' Ctrli Pvmt S0UTH 24.1' S1" N of ctrli of Pvmt. in Face of Cor Fen Post S3W 54.2' SURVEYOR'S MICHIGAN REGISTRATION NO. 10068 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY CHIEF OF SURVEY PARTY DATE SIGNED BY CHIEF OF SURVEY PARTY					
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Found old stake point 33' E of Fence corner & in line with L of Road South. Found metal attraction below surface of blacktop at intersection of roads. Did not excavate but should be okay for corner. Corner set by proportionate measurement between section corners. Found 1" pipe at corner about 25' North of centerline of road. Said to be the corner by local testimony and other surveyor's established to perpetuate locating the position of the corner: E-3 Set DNR Monument P. K. Nail in blacktop Set DNR Monument 10" B1. Ash N70E 20.2 Face of 6" Scth Pine S35E 49.5' 13" Maple S04W 12.7 16" Maple N15E 24.3 Face of P.P. S61W 91.6' 10" Maple S75E 16.1 G-5 Set DNR Monument Set 1"x30" Pipe 15" Poplar S77E 16.9' 8" TW Maple S40L 76.8' Sign Post S 5W 9.5' Ctrli Pvmt S0UTH 24.1' S1" N of ctrli of Pvmt. in Face of Cor Fen Post S3W 54.2' SURVEYOR'S MICHIGAN REGISTRATION NO. 10068 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY CHIEF OF SURVEY PARTY DATE SIGNED BY CHIEF OF SURVEY PARTY					
Found metal attraction below surface of blacktop at intersection of roads. Did not excavate but should be okay for corner. Corner set by proportionate measurement between section corners. Found 1" pipe at corner about 25' North of centerline of road. Said to be the corner by local testimony and other surveyors. The corner by local testimony and other surveyors between section corners. F-3 Set DNR Monument P.K. Nail in blacktop Set DNR Monument Set DNR Monument Set DNR Monument Set 1"x30" Pipe Set DNR Monument Set 1"x30" Pipe The corner by local testimony and other surveyors. Soll the corner between section corners. F-3 Set DNR Monument Set DNR Monument Set 1"x30" Pipe The corner between section corners. Set DNR Monument Set 1"x30" Pipe Set 1"x30" Pipe Set 1"x30" Pipe Set 1"x30" Pipe DATE Set DNR Monument Set 1"x30" Pipe DATE Set DNR Monument Set 1"x30" Pipe Set 1"x3					
Corner set by proportionate measurement between section corners. Found 1" pipe at corner about 25' North of centerline of road. Said to be the corner by local testimony and other surveyors sublished to perpetuate locating the position of the corner: E-3 Set DNR Monument P.K.Nail in blacktop Set DNR Monument 10" B1.Ash N70E 20.2 Face of 6" Scth Pine S35E 49.5' 13" Maple S04W 12.7 16" Maple N15E 24.3 Face of P.P. S61W 91.6' 10" Maple S75E 16.1 G-5 Set DNR Monument Set 1"x30" Pipe 15" Poplar S77E 16.9' 8" Tw Maple S40L 76.8' Sign Post S 5W 9.5' Ctrli Pvmt S0uTH 24.1' 24.5' N of ctrli of Pvmt. in Face of Cor Fen Post S3W 54.2' SIGNED BY SURVEYOR'S MICHIGAN REGISTRATION NO. 10068 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY CHIEF OF SURVEY PARTY DATE CHIEF OF SURVEY PARTY DATE	Found old stake point 33' E of Fence corner & in line with & of Road South.				
Found 1" pipe at corner about 25' North of centerline of road. Said to be the corner by local testimony and other surveyors stablished to perpetuate locating the position of the corner: E-3 Set DNR Monument P. K. Nail in blacktop Set DNR Monument 10" Bl. Ash N70E 20.2 Face of 6" Scth Pine S35E 49.5' 13" Maple S04W 12.7 16" Maple N15E 24.3 Face of P.P. S61W 91.6' 10" Maple S75E 16.1 G-5 Set DNR Monument Set l"x30" Pipe 15" Poplar S77E 16.9' 8" Tw Maple S40E 76.8' Sign Post S 5W 9.5' Ctrli Pvmt S0uTH 24.1' 24.5' N of ctrli of Pvmt. in Face of Cor Fen Post S3W 54.2' Line with gravel rd South SIGNED BY CHIEF OF SURVEY PARTY DATE SIGNED BY CHIEF OF SURVEY PARTY DATE G-3 F-3 F-3 F-3 F-3 F-4 F-3 F-3 F					
Set DNR Monument 10" B1.Ash N70E 20.2 Face of 6" Scth Pine S35E 49.5' 13" Maple S04W 12.7 16" Maple N15E 24.3 Face of P.P. S61W 91.6' 10" Maple S75E 16.1 G-5 Set DNR Monument Set 1"x30" Pipe 15" Poplar S77E 16.9' 8" Tw Maple S40E 76.8' Sign Post S 5W 9.5' Ctrli Pvmt S0UTH 24.1' 24.5' N of ctrli of Pvmt. in Face of Cor Fen Post S3W 54.2' Nof ctrli of Pvmt. in Face of Cor Fen Post S3W 54.2' SURVEYOR'S MICHIGAN REGISTRATION NO. 10068 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY CHIEF OF SURVEY PARTY DATE CHIEF OF SURVEY PARTY DATE	Corner set by proportionate measurement between section corners.				
Set DNR Monument 10" B1.Ash N70E 20.2 Face of 6" Scth Pine S35E 49.5' 13" Maple S04W 12.7 16" Maple N15E 24.3 Face of P.P. S61W 91.6' 10" Maple S75E 16.1 G-5 Set DNR Monument Set 1"x30" Pipe 15" Poplar S77E 16.9' 8" Tw Maple S40E 76.8' Sign Post S 5W 9.5' Ctrli Pvmt S0UTH 24.1' 24.5' N of ctrli of Pvmt. in Face of Cor Fen Post S3W 54.2' Nof ctrli of Pvmt. in Face of Cor Fen Post S3W 54.2' SURVEYOR'S MICHIGAN REGISTRATION NO. 10068 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY CHIEF OF SURVEY PARTY DATE CHIEF OF SURVEY PARTY DATE	Found 1" pipe at corner about 25' North of centerline of road. Said to be the corner by local testimony and other surveyors. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.				
Set DNR Monument Set 1"x30" Pipe 15" Poplar S77E 16.9' 8" Tw Maple S40£ 76.8' Sign Post S 5W 9.5' Ctrli Pvmt SOUTH 24.1' 24.5' N of ctrli of Pvmt. in Face of Cor Fen Post S3W 54.2' line with gravel rd South SIGNED BY CHIEF OF SURVEY PARTY DATE CHIEF OF SURVEY PARTY DATE CHIEF OF SURVEY PARTY DATE	E-3 Set DNR Monument	E-5 P.K.Nail in blacki	top Set Di	F-3 NR Monument	
Set DNR Monument Set 1"x30" Pipe 15" Poplar S77E 16.9' 8" Tw Maple S40£ 76.8' Sign Post S 5W 9.5' Ctrli Pvmt SOUTH 24.1' 24.5' N of ctrli of Pvmt. in Face of Cor Fen Post S3W 54.2' Tine with gravel rd South SIGNED BY SURVEYOR'S MICHIGAN REGISTRATION NO. 10068 FOR STATE AND UNITED STATES AGENCIES: SIGNED BY CHIEF OF SURVEY PARTY DATE CHIEF OF SURVEY PARTY				aple S/SE Ib.I	
FOR STATE AND UNITED STATES AGENCIES: SIGNED BY DATE	Sign Post S 5W 24.5' N of ctrli of Pv	Set 1"x30" 6.9' 8" Tw Map1 9.5' Ctrli Pvmt mt. in Face of Co	Pipe e S40L 76.8' : S0UTH 24.1' or Fen Post S3W 54.2'	LAJIO 🕯 💥 🗒	
FOR STATE AND UNITED STATES AGENCIES: SIGNED BY DATE	SURVEYOR'S MICHIGAN REGISTRATION NO. 10068				
CHIEF OF SURVEY PARTY					
	SIGNED BY DATE				
(SEAL I			DATE	(SFAL)	
				, Garage 1	

-5

⁻-3

-5

-3

G-5