

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T47-48 NR. 33-34-N

_____ COUNTY

DESCRIPTION OF CORNER Sec. corner for sections 1, 4, 31, 36 also 3rd. corner

DESCRIPTION OF CORNER MONUMENT 1" pine with 4" brass cap

WITNESSES TO CORNER 3-26-58

10" cedar (dead) S 57° E 23 links. Marked "1148"

All timber dead in vicinity.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR

RESTORED. Replaced from one white pine S. T. bearing S 57° E 23 links. Very poor condition. Also found unrecorded cedar S. T. bearing S 40° E 16 links in poor condition. Corner lies in dead beaver run. Found by forestry division survey crew.

SURVEYORS SEAL

SIGNED Billy D. Buckler
Billy D. Buckler
REGISTERED LAND SURVEYOR DATE 4-30-59