	LAND	CORNER RECOR	PDATION CERTIF	ICATE					
For corners in	FIIII	ng Requirement of A	Act 74, Mich. P.A.	1970					
Baraga									
(County)	Located In:	Corner Code #							
1. Public Land Survey	T <u>47N</u> R T <u>47N</u> R TR	33W D5	_						
2. Property Controlling in Section3. Miscellaneous Property in Sec.	TR S TR S TR S TR			. F	Register	of Deeds	Stamp &	File Nur	mber
4. Lot No, Recor	ded Plat			_					
5. Private Claims			-	1 A	B C	D E F	G H	ΙJΚ	_ <u>L </u>
	D5	Dec 30 2002		2	- 6	- 5 4 -	i	<u> </u>	— <u>i</u> –
ı, Stephan J. Szyszkoski	E1	Dec 16 2002	.	3 -	++	1-1-1	1 1-	 	+
requirements of P.A. 74, Michiga conformance with regulations and United States Department of the lithat the corner points mentioned Board of Land Surveyors or by recovered, found as expressed be	in P.A. of 1970, the corn rules therefore as require interior, Bureau of Land N in lines 3, 4 and 5 above a Decree of a Court of	er points mentioned in lin- ed in the current manual of fanagement or by a decree were in conformance with	survey instructions of the of a Court of Law and / the rules of the Michiga	in ne 5 or 6	-18	1716-	15-	-1114142323	-12- -13- -24-
NOTE: Not more than 2 corners, all in the same town and range, may be recorded				9	++-		 		
on this certificate.				10	-30	-2928-	27—	26	2 ¹ 5
				11	1-1-	+	 		
				12	-31	-3 ² 3 ³ -	34_	35-	3 ['] 6
scribed post recovered at rec Cedar NO8W 146 links, 12" Ced (D5) Quarter corner common to 1932: Record of Northern Pape states "H. Peryam and S.Wickm N58E 29." 1965: Billy D. Bu Stake marked B.T. in stump (C Paper Mills). 11/3/64. 8" S	ar NO8E 169 links. Sections 8-17. 185 r Mills (NPM) states an found post, Cole' ckler RLS states "Th edar) N68E 6 links w	2: Established by Fra "Cole and Ellison fo s register. Probable is corner was placed hich has faces but no	uncis Houck: Cedar ound 14" Cedar N68E ced B.T. down. Se at base of blown do o iron marks visible	14 in dia 6 standi et pipe a ewn Cedar	am. qr d ng dead. t post. which m	or. Cedar Set post Ash 6 SIS	12 N68E ". 1954 W 21.3,	6 links : NPM re Red Map : r tree.	cord 8
B. Description of corner evid	lence found and/or m	ethod applied in restori	ng or reestablishing (corner:					
(E1) Recovered the 1959 monum submerged W.Pine stump remain at record bearing and distanc about 25' distant. (D5) Found the Northern Paper 1965 witness trees. The Mapl	ent under 18" of wat s of what is probabl e. Left the monumen Mills monument layi	er in a beaver pond, y the original BT not at in place and made n ing nearly horizontal!	in good condition, ted above. Both 199 new witnesses as des	and at room of the second and at room of the second and the second	N8Ts wer elow.	re recover A beaver lo ment to be	ed in goo odg e bear	d condit s NW'ly	·
C Description of monument (E1) Found 1" I.pipe with 4" Dept. of Conservation cap. Bearing and continuous and c	brass MI (D	sories established to pe 25) Found 1" iron pipe orthern Paper Mills ca cribed, and set measu	e with 2" brass ap. Blazed,		0 TED	MICHIG			
•	S4 MBT" 9" S32 MBT" 8" 19. 9" Izes Di Izes Th It bearings wi st adjacent. Ba	Cedar S82E 27.0' Cedar N80M 23.8' Cedar N48M 39.3' istances are to nail the 1964 witness: 8" Mith scribing visible. agnetic. Set sq'd ce	"1/4S NBT" do do with tag. aple N60E 19.1' 8earings are dar post adjacent. Date	** 100	SZYS: SUR' 33	ZKOSKI AND VEYOR No. 3986	100	· ••.	
Surveyor's Michigan License	No. 33	3986							