Cons. 4047 Rev. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. <u>47</u> N. R. <u>34</u>W

	Baraga	COUNTY
DESCRIPTION OF CORNER _ 1/4 corner between Section	ns 17 & 20	
CORNER HONUMENT lu pipe with 4m aluminum o	cap	<del></del>
DATE MONUMENT PLACED AND WITHESSED November 2, 19	966	
WITHESSES TO CORNER 8" Cedar ( S NBT) S	12°E 24.8	
8" Cedar (± S NBT) N		
AND CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced from one cedar B.T.; S55°W 5 lks. Found several old blazes and signatures at corner site.

Corner lies on top of a narrow ridge in swamp, about 25 feet high.

SURVEYOR'S SEAL

SIGNED Silly Q. Suchles DATE 3/29/66