

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N.R. 34W


Baraga COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 5 & 6

CORNER MONUMENT 1 1/2" x 30" Iron Pipe, buried in road

DATE MONUMENT PLACED AND WITNESSED October 31, 1966

WITNESSES TO CORNER..... 8" Hard Maple (1/4 S NBT) S80°E 34.8'



5" Hard Maple (1/4 S NBT) S74°W 41.7'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established by proportionate measure between Section corners to North and South.

Corner lies south of road to east.

SURVEYOR'S SEAL

SIGNED Billy O. Buckles DATE 3/27/66
REGISTERED LAND SURVEYOR