

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 47 N.R. 34W


Baraga COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 5 & 8

CORNER MONUMENT 14" squared cedar

DATE MONUMENT PLACED AND WITNESSED November 2, 1966

WITNESSES TO CORNER..... 12" Cedar (1/4 S NBT) N38°E 8.8'



13" Cedar (1/4 S NBT) S86°W 15.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-witnessed as marked by unknown persons about 60 years ago.

Found several large cedars in vicinity but no positive identification.

Corner lies in cedar swamp.

SURVEYOR'S SEAL

SIGNED Billy O. Buckles DATE 3/29/69  
REGISTERED LAND SURVEYOR