Cons. 4047 Rev. 10/60

CIRCLE CORNER REGISTERED

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

Baraga COUNTY

DESCRIPTION OF CORNER 1/4 cor, between Sec. 24 & 25

CORNER MONUMENT 1* I. D. x 36* iron pipe with 2* brass cap

DATE MONUMENT PLACED AND WITHESSED August 30, 1968

WITHESSES TO CORNER.... Cedar 7 N16W 12 1ks. *1/4S NBT**

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-witnessed the above monument as placed by Northern Paper Mills personnel, probably in early 1950's. Corner had been set from an original BT, Tam. 12 S3E 6. Stump still in place, badly rotted, no identifying marks left, but there may have been some when corner was set. Also found scraps of an old cedar post in the muck, possibly the original post, and a more recent squared cedar post. Also found a $1\frac{1}{4}$ " I. D. iron pipe at corner, set by mnknown surveyor. A 3/4" I. D. iron pipe bearing an aluminum plug marked WMPCo. No. 57, 1931, is located S82W 84 links from corner.

Northern Paper Mills had re-witnessed corner as follows:

Cedar 10 S32½W 52½ lks. "LS, S25, BT" Cedar 12 N24 W 57½ lks. "LS, S24, BT"

Names of persons present on this date when corner was re-witnessed: A. O. Enger, J. E. Julkonen, W. A. Dellies.
SURVEYOR'S SEAL

SIGNED Arthur O. Engr DATE 10/29/65