

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 47 N.R. 34W


Baraga COUNTY

DESCRIPTION OF CORNER 1/4 cor. bet. secs. 14-23

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 3/15/66

WITNESSES TO CORNER..... 12" Hard Maple (1/8 S NBT) N52°E, 24.9'



10" Soft Maple (1/8 S NBT) N60°W, 29.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced corner at an old wood post set by unknown surveyor. Found no evidence of original witnesses. Position checks with other corners in area.

Cor. lies on east side of slope and about one chain west of swamp edge.

Logging road is 2 1/2 chs. west of corner

SURVEYOR'S SEAL

SIGNED Billy J. Buckley DATE 2/8/67
REGISTERED LAND SURVEYOR