

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N.R. 34W


Baraga COUNTY

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 14-15-22-23

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 3/15/66

WITNESSES TO CORNER..... 13" B. Spruce (S14 NBT) N2°E, 79.2'



14" B. Spruce (S23 NBT) S5°E, 38.1'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced corner an old wood post with blazed lines to north, east and west.

Distance south and west to a small brook check well

Corner lies in wet tag alder bottom.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 2/8/67  
REGISTERED LAND SURVEYOR