

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T48... NR 33 W...

Baraga COUNTY

DESCRIPTION OF CORNER 1/4 corner for sections 5 - 8

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 11" cedar N 30°, W 60 links. Marked "1/4 S N B T"

10" cedar N 18°, E 91 links. Marked "1/4 S N B T"

4-2-58

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR

RESTORED. Replaced from two original B. T.'s. Cedar bearing N 42°, W 13 links, stump cut high, B. T. in good condition. Y. Birch bearing S 20°, E 25 links, stump in poor condition. Corner found by L. Stevens, District Forester.

SURVEYORS SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 4-30-59
REGISTERED LAND SURVEYOR