## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T47-48 NR 34 V

			Ba	raga	COUNTY
DESCRIPTION	OF	CORNER	Section corner common	to_Sec. !s_2-3-34	-35
DESCRIPTION	OF	CORNER	MONUMENT_1"_pipe_wi	th /i" brass cap	
WIT TNESSES	TQ	CORNER	8"_CedarS	3 40° E	21 links
			6"_Cedar	=	13. 11nks
			12" W. Pine N	78 E 5 NET"	68 links
			"5 )	)) Wur	
					<del> </del>

## DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced corner from one spruce B.T. bearing S 32° W, 18 links. B.T. has been cut high. All scribe marks visible. B.T. in excellent condition.

Found boulder and wood post in place with Ford Motor Co. location poster at corner.

Corner found by L. Stevens, District Forester.

Corner placed and witnessed Dec. 10, 1957.

SURVEYORS SEAL

SIGNED\_Silly Duckeles DATE 12/19/57
REGISTERED LAND SURVEYOR