ONS. 4047

MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T47-48 NR 34 V ...

	Barasa COUNTY
DESCRIPTION OF CORNE	R Sec. corner for sections 1, 2, 35, 36
DESCRIPTION OF CORNER	MONUMENT 1" pipe with 4" brass cap
WITNESSES TO CORNER	4-2-58
	9" hard maple S 56°, E 95 links. Harked "SIMBI"
	9" hard maple N 24°, W 92½ links. Harked "535NFT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR

RESTORED. Replaced from one y. birch b. T. bearing N 31°, W 21 links. Free green, rotted inside. Found by Forestry Division Survey Crew. Position checks with corners along Twp. line east and west.

SURVEYORS SEAL

Billy D. Buckles

REGISTERED LAND SURVEYOR

DATE 4-30-59

.