MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_49 NR_32 W

				Baraga	COUNT
DESCRIPTION	OF	CORNER	1/4 corner be	tween Sec. is 13-14	
DESCRIPTION	OF	CORNER	MONUMENT	l" pipe with 4" bras	s cap
WIT TNESSES	то	CORNER	10" Y. Birch	n 88° e Beribed 71/4 5 e	39 links
			12" Cedar	n 57° w	
				scribed #1/4 S B	Tu

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found 1/4 corner; cedar post in place. Y. Birch B.T. bearing N 11° W 25 links (green) in excellent condition.

Found two new witnesses marked about 10 years ago.

SURVEYORS SEAL

SIGNED Silly Suchles DATE 7/31/57