

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 49 NR. 34

Benaga COUNTY

DESCRIPTION OF CORNER 1/4 corner between sections 15 - 16

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 7-17-58

9" jack pine S 84°, w 46 links. Marked "SNET"

7" jack pine S 83°, S 36 links. Marked "SNET"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED. Re-established corner midway and on line between two section corners.  
Found no evidence of original corner. Corner witnessed with L. Stevens, District  
Forester.

SURVEYORS SEAL

*Billy D. Buckler*  
SIGNED Billy D. Buckler DATE 5-1-59  
REGISTERED LAND SURVEYOR