MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T_49__ NR__34_7/_

	Barana COUNTY
DESCRIPTION OF CORNER	Section corner 16 - 17 - 20 - 21
DESCRIPTION OF CORNER	MONUMENT_l" pipe with ~" prass cap
WITNESSES TO CORNER _	7-22-58
	6" jack pine 3 7.0, W lll links rhed "820% T"
	_6"_jsck_pine_S_320, F_01_linksark31_"821837"
	6" jack gine N. 46°, E. 23 links. Marked "Cloyer"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. Re-established corner by single proportionate measure on east and west center line of township according to method used to originally subdivide twp. Found no evidence of corner. Corner placed and witnessed with L. stevens, District Forester.

SURVEYORS SEAL

SIGNED __

Billy I. Buckler
REGISTERED LAND SURVEYOR

DATE 5-1-59_ _