

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49. NR. 34 W. . .

----- Baraga ----- COUNTY

DESCRIPTION OF CORNER ----- Section corner 15, 16, 21, 22 -----

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap -----

WITNESSES TO CORNER 7-17-58 -----

7" jack pine N 36°, W 21 links. Marked "S16"SP" -----

8" jack pine N 41°, E 79 links. Marked "S15"SP" -----

5" jack pine S 62°, W 42 links. Marked "S21"SP" -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR

RESTORED. Re-established corner from section corner 1 mile north, section corner 1 mile south, sup. edge 9.0 chains west, sup. edge 1.0 chains north. No evidence of jack pine bearing trees. Area badly burned. Witnessed corner with L. Stevens, District Forester.

SURVEYORS SEAL

Billy D. Buckler
SIGNED Billy D. Buckler ----- DATE 5-1-59 -----
REGISTERED LAND SURVEYOR