## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T\_49 NR\_34 W = T 49 NR 35 W

			COUNTY
DESCRIPTION	OF	CORNER	Section Corner common to Sections 7,18,12,13
DESCRIPTION	OF	CORNER	MONUMENT_1" Pipe with 4" Brass cap
WITTNESSES	то	CORNER	_4"_ROek8_29 JF15_Links
			26" Pine Stamp - H S E - 37 Links
			6" R. Oak - H 57 E - 39 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a a resurvey of the North half of this Township. Two original B.T.'s in place, both badly burned.

Corner was placed and witnessed June 21, 1950.

SURVEYOR'S SEAL

SIGNED Sum C. Sun mater DATE 7/3/51 \_