

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 50 N.R. 32-33 W


Baraga COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 18, 19, 13, 24

CORNER MONUMENT 1" Iron Pipe

DATE MONUMENT PLACED AND WITNESSED 8/17/61

WITNESSES TO CORNER.... 5" Soft Maple (S 18 NBT) North 13 1/2 Links



8" Soft Maple (S 24 NBT) S 86° W 24 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-witnessed as set by unknown surveyor. Found wood post, iron pipe and location tag at corner. Corner lies on west edge of road.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE August 18, 1961
REGISTERED LAND SURVEYOR
Billy D. Buckler