Cons. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. ____50 N.R. ___32 W

			Baraga	COUNTY
DESCRIPTION OF CORNER	1/4 corner between Se	ctions 7 and	18	
CORNER MONUMENT	Steel Fence Post			
DATE MONUMENT PLACED A	ND WITHESSED8	/17/61		
WITHESSES TO CORNER	10" Soft Maple (Twin)	(1/4S NBT)	N 60° W	77 Links
N18	9 <u>" Soft Maple (TWin)</u>			
†	AND			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-witnessed as set by previous survey, probably by Celotex Corporation. Position checks well with Corners both East and West. Corner lies on NW side of old beaver dam.

SURVEYOR'S SEAL

SIGNED Silly Suchler DATE August 18, 1961

PÉGISTERED LAND SURVEYOR

Billy D. Buckler