APR 0 8 1995

C	DMMISSIMMC	ON LAN		RECORDATION C				•				
For corners	in Baraga		-	ent of Act 74, Micl	n. P.A. 1970							
1. Public L	(County) and Survey	Τ		G-1	OF I AND CORI	RECEIVED FOR RECORD THIS 28TH DA OF DECEMBER A.D. 1995 AT 10:30 AI AND RECORDED IN LIBER 4 OF LAND CORNER RECORDATION ON PAGES 589 - 590.			30 AM			
in Section 3. Miscella		T ST ST ST	R R R R			AGA C	OUNT	Y RE		R O	DE	
4. Lot No.		Recorded Plat										
5. Private (Claims					- A	-6	_5		3 H 3-	2-	<u> </u>
Michael	Mileski	, in a field survey on _	Decembe	ار 	95	3 4 -	-7	-8	— 9—	——10— ——1	11-	12-
5 above were Decree of a C as expressed NOTE: Not on the A. Descrip	e in conformance ourt of Law; es below: more than 4 chis certificate. tion of original	of a Court of Law and/or ee with the rules of the it tablished, re-established corners, all in the same al monument and access or common to Se	vichigan Board , monumented, town and ran essories and/	of Professional Survey onumented, recove age, may be recorded or subsequent restor	ors or by a ered, found	10	-303131	-20 -29 -32 -32	-21	-22- -27- -34-	23-	25
	ee back of		APPRO P., E	VED LAND CORNER A. 345 OF 1990 Baraga County D-19-95	• •							
B. Descript	tion of corner	evidence found and/	or method ap	plied in restoring or r	reestablishing	corne	:					
3-1; Clos	sing Corne	r common to Se	ctions 3 an	d 4, T50N, R33\	N.							
		" aluminum pipe s. The monume								v		

(U.S. = 159.72') west of a creek. This monument is accepted as a careful and faithful reestablishment of the position of the original corner.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- G-1; Closing Corner common to Sections 3 and 4, T50N, R33W.

See back of form.



Signed by_	is all	les	ON O	ilse

Surveyor's Michigan License No. 39091

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 23, 1971 FEVISED MAY 14, 1975 REVISED JAN., 1983

- A. Description of original monument and accessories and/or subsequent restoration:
 - G-1; Closing Corner common to Sections 3 and 4, T50N, R33W.

Originally established during U.S. Survey conducted by William Burt, D.S. in 1849 and monumented with a cedar post witnessed by a

Cedar 10 S47°E 5 lks. (Gone)

and a

Cedar 5 S33°W 6 lks. (Gone)

This corner was reestablished at proportionate distance by Stephen Douglas of the Bureau of Land Management during the course of a survey conducted from 13 May 1987 to 4 November 1987 and approved 24 March 1989. Mr. Douglas monumented the corner with a 2½ "aluminum pipe with 3" brass cap appropriately stamped as to location and noted the following new bearing trees:

Maple 5 S10°E 171/2 lks.

and a

Maple 7 S70°W 211/2 lks.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - G-1; Closing Corner common to Sections 3 and 4, T50N, R33W.

Left existing monument in place adding "PA 345 1995" to the brass cap.

Set 60d spike	E/side	7" Red Maple	N34°E	27.09'
Set 60d spike (BLM NBT, add			S10°E	11.55'
Set 60d spike	SE/side	10" Red Maple	S58°W	28.67'
Set 60d spike (BLM NBT, add		•	S68°W	14.19 [,]
Set 60d spike	NE/side	8" Red Maple	N37°W	20.95'

The above three non-BLM new bearing trees are marked with upper and lower face blazes and scribed "NBT".