## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

DESCRIPTION OF CORNER 1/4 corner for sections 31/32

CORNER MONUMENT 1" iron pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITHESSED 9-12-62

WITHESSES TO CORNER..... 9" W. Birch (NBT)(1/4S) S52°W, 15½ links

9" Maple (NBT) (1/4 S) S25°E, 39 links

AND

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from old wood post which checks within a few links of being midway and on line between section corners. No original evidence.

SURVEYOR'S SEAL

CIRCLE CORNER REGISTERED

REGISTERED LAND SURVEYOR
Billy D. Buckler

DATE <u>April 23, 1963</u>