

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 50 N.R. 34W

Baraga COUNTY


DESCRIPTION OF CORNER Section Corner for sections

20	21
29	28

CORNER MONUMENT 1" Iron pipe with 4" Brass Cap.

DATE MONUMENT PLACED AND WITNESSED 5-18-61

WITNESSES TO CORNER..... 7" Soft Maple (S20 NBT) N 49°W 45 1/2 links



7" Oak (S28 NBT) S 60°W 40 1/2 links

8" Y. Pine (S29 NBT) S 47°E 103 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from iron pipe and down blazed pine stub. Pipe checks well with corners in vicinity. No original evidence.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE December 21, 1961
REGISTERED LAND SURVEYOR
Billy D. Buckler