

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 50 N.R. 34W


Baraga COUNTY

DESCRIPTION OF CORNER 1/4 Cor. between Secs' 17-18

CORNER MONUMENT 1" Pipe with 4" brass Cap.

DATE MONUMENT PLACED AND WITNESSED 5-18-61 with R. Hinds

WITNESSES TO CORNER..... 9" Hard Maple (1/4 S NBT) S 15°W 29 Links



9" Y. Birch " " East 41 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from one Hemlock stump bottom bearing S25 E 21 links.
Position fits well with Corner 1/2 mile South.
Cor. lies on N-S Paint Line.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE December 27, 1961
REGISTERED LAND SURVEYOR
Billy D. Buckler