

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T 51 NR 30 W
T 52 NR 30 W

----- Baraga ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 5, 6, 31, 32 -----

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap -----

WITNESSES TO CORNER -----

12" S. Maple - N 45 E - 34 Links -----

16" Hemlock - S 50 W - 20 Links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was pointed out to me by Leroy Stevens, District Forester, of Baraga. One original B.T. still in place, in good condition. Original corner, (squared Cedar) in place, in good condition.

Corner was placed and witnessed June 18, 1953.

SURVEYORS SEAL

SIGNED *James C. DePinto* DATE 1/21/54
REGISTERED LAND SURVEYOR