

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 51-52 N.R. 30 W


Baraga COUNTY

DESCRIPTION OF CORNER Section Corner for Secs. 3-4, T51N R30W and 33-34 T52N R30W

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 7/14/65 with Magnuson

WITNESSES TO CORNER..... 18" Cedar (S33 MBT), N 56° W, 35 1/2 Iks.



18" Cedar (S3 MBT), S 33° E, 32 Iks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was set at wood post and 3/4" iron pipe witnessed by unknown Surveyor.
(2) two possible Cedar BT's down and rotted in proper distance and bearing.
BT's by unknown Surveyor:
12" Hemlock, S 64° W, 27 Iks.
8" Hemlock, N 15° W, 09 Iks.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 9/10/65
REGISTERED LAND SURVEYOR