

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 51 N.R. 30 W


Baraga COUNTY

DESCRIPTION OF CORNER 1/4 Corner for Secs. 5/8

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 7/15/65 with J. Magnuson

WITNESSES TO CORNER..... 16" Cedar (1/4S NBT), N 30° E, 29 1/2 Lks.



CIRCLE CORNER REGISTERED

18" Hemlock (1/4 NBT), S 20° E, 40 1/2 Lks.

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was set from H. Maple stub Original BT (Sugar 5" N 35° W, 19 Lks.)  
Scribe marks on lower face. (Cedar 6" S 65° E, 11 Lks.) has overgrowth of face  
and checks well. 1 1/2" iron pipe was found at corner.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 9/10/1965  
Frank J. Bray  
REGISTERED LAND SURVEYOR