## STATE OF MICHIGAN DEPARTMENT 0F **NATURAL RESOURCES**

## LAND CORNER RECORD

	Baraga 	COUNTY
	T	R
DESCRIPTION OF CORNER Section Corner 7, 8, 17		
CORNER MONUMENT 1" I.D. x 36" iron pipe with 4"	" aluminum cap	
DATE MONUMENT PLACED AND WITNESSED September	1, 1970	
WITNESSES TO CORNER Cedar 8 S39°E 13.3	ft. "S17, NBT"	
N		
CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found a squared and scribed cedar post in place, as set by unknown party, with following NBT's: Cedar 9 N5 E 6.7 ft., "S7, BT" and Cedar 7 N34°E 8.5 ft., "S8, BT".

Accepted scribed post as found, as it checks reasonably well with other corners in Section 18. No trace of meander corner recorded in original notes as 3.47 ch. north of corner, but shoreline of Lake Superior appears to have changed since the original survey. Found an 8" cedar N46°E 18 ft. with Celotex Corp. location tag.

SURVEYOR'S SEAL

SIGNED

September 23, 1971

DISTRIBUTION:

Arthur O. Enger

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing