

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Baraga COUNTY


T 51N R 31-32W

DESCRIPTION OF CORNER Section Corner 13, 18, 19, and 24

CORNER MONUMENT Same monuments as found. Re-witnessed pipe as listed below.

DATE MONUMENT PLACED AND WITNESSED August 18, 1970

WITNESSES TO CORNER..... Cedar 9 N39°W 22.0 ft. "S13, NBT"



Cedar 12 S40°E 30.2 ft. "S19, NBT"

Y.Birch 6 S51°W 21.1 ft. "S24, NBT"

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found a 3/4" iron pipe and scribed wood post in place, as set by unknown party. Corner perpetuated as found.

Three original BT's found and identified on above date.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Arthur O. Enger
REGISTERED LAND SURVEYOR
Arthur O. Enger

DATE

September 28, 1971

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing